



DEPARTMENT OF
WATER RESOURCES

DELTA AREA *Fact Sheet* **Site 21.8**

Critical Levee Erosion Site

Emergency Levee Repairs

Location

River: Cache Slough

River Mile: 21.8

Latitude/Longitude:

38.270878/-121.706716

Nearest Impact Area:

Rio Vista

County: Solano

Bank: Right

Type of Damage

Bank erosion

Length of Repair

2,500 feet (approximate)

Repair Type

Rock slope protection

Lead Agency

Department of Water Resources

**For further information,
please contact:**

Elizabeth Scott
DWR Public Affairs Office
(916) 835-5344
leveerepair@water.ca.gov

DEPARTMENT OF WATER RESOURCES
PO Box 942836, Sacramento, CA 94236

www.levees.water.ca.gov

